



Maricopa County

Air Quality Department

Compliance Division
1001 North Central Ave.,
Suite 125
Phoenix, Arizona 85004
Phone: 602-506-6010
Fax: 602-506-2163

Dear Responsible Party:

RE: Inspection Report - No Violation Noted

You are receiving this letter as a result of an inspection that was conducted at your site/facility. Enclosed with this letter is your Inspection Report to notify you of the results of your inspection.

The information located on the back page of this letter will clarify the acronyms and policies referenced in the Inspection Report. Further information about the Maricopa County Air Quality Department (MCAQD) Rules and Regulations can be found at the MCAQD website: www.maricopa.gov/aq

Additional information about how you can improve air quality in Maricopa County can be found at www.CleanAirMakeMore.com

If you have any questions, you may contact the inspector noted on your Inspection Report or contact a Maricopa County Air Quality Department Compliance Supervisor, at (602) 506-6734.

Thank you,

Air Quality Compliance Division
602-506-6734

Acronyms used in the Inspection Report:

\leq - Less than or equal to	CM - Certified Mail	NTV – Non Title V
\geq - Greater than or equal to	COMS - Continuous Opacity Monitoring System	O&M Plan – Operations and Maintenance Plan
AAP - Area Accessible to the Public	DCP – Dust Control Plan	PC – Permit Condition
ACWM – Asbestos Containing Waste Material	DGO – Dust Generating Operation	RACM – Regulated Asbestos Containing Material
ASHARA – Asbestos School Hazard Abatement Reauthorization Act	ECS – Emissions Control System	RM - Regular Mail
AHERA – Asbestos Hazard Emergency Response Act	HAP – Hazardous Air Pollutant	Stab. - Stabilize
ATI - At the time of inspection	HAPRACT – Hazardous Air Pollutant Reasonable Available Control Technology	TO - Track Out
AZMACT – Arizona Maximum Achievable Control Technology	HT - Haul Truck	TOCD – Track Out Control Device
CARB – California Air Resource Board	N/A - Not Applicable	VEE - Visible Emissions Evaluation
CEMS – Continuous Emission Monitoring System	N/O - Not Observed	VOC – Volatile Organic Compound

The owner/operator is ultimately responsible for maintaining the site/facility in compliance with Maricopa County rules and regulations at all times.

INSPECTION REPORT



Maricopa County Air Quality Department
1001 N. Central Avenue, Suite 125
Phoenix, AZ 85004
Phone: (602) 506-6010 Fax: (602) 506-2537
www.maricopa.gov/aq

Date: 26-Mar-14
Start Time: 1125 hrs End Time: 1135 hrs
Inspector: Shannon Klimek #92
Phone: 602.527.6288
Email: klimeks@mail.maricopa.gov

Inspection Result:

No Violations Noted

Inspection Type: Partial inspection On-site

Inspection Purpose: Complaint

☒ Compliant CL

Complaint Number: 254788

Permit Number:

040136

Hickman's Egg Ranch, Inc.

6515 S. Jackrabbit Trail

Buckeye

AZ 85326

Site Name: Hickmans Egg Ranch

Site Address:

32425 W Salome Hwy

City:

Arlington, AZ

Site Contact: Compliance Manager, Shari Yeatts

Phone:

623.872.2358

Inspection Rights Notification:

Not On Site

Comments

On-site Complaint response regarding odor from Hickman's Egg Ranch, Inc. From off -site I was able to detect an acrid odor from the North facility.

When I arrived on site, I telephoned Paul Yeatts, Director of Construction for Hickman's Egg Ranch, Inc. Mr. Yeatts explained that my contact, Compliance Manager, Shari Yeatts is currently unavailable.

I explained the purpose of my inspection and my observations.

I did not observe any violations during my inspection.

End report.

Additional documents associated with this inspection report:

1) Field notes

☐ DOCUMENT REVISED

Delivery Method:

Date: 08-Apr-14

Regular Mail

OFFICE USE

rec: SK

rev: